

BID TAB: AS-2020-3, Exterior Painting of Camarillo Ranch House	Ray-Mac Painting, Inc.	VLA Construction Inc.
Owner: City of Camarillo	79 Daily Drive #189	22815 Ventura Blvd. #157
Bid Opening: January 7, 2021	Camarillo, CA 93010	Woodland Hills, CA 91364
	License #888007	License #1040399
Item Description		
Wood Surfaces - Siding/Trim 1 primer coat & 1 finish coat		
Cost - Labor	\$ 16,750.00	\$ 43,700.00
Cost- Material	\$ 1,500.00	\$ 4,000.00
Number of Gallons	60	90
Second finish coat		
Cost - Labor	\$ 8,250.00	\$ 3,500.00
Cost- Material	\$ 500.00	\$ 1,800.00
Number of Gallons	20	45
Wood Surfaces - Deck 2 finish coats		
Cost - Labor	\$ 2,000.00	\$ 8,900.00
Cost - Material	\$ 350.00	\$ 600.00
Number of Gallons	7	10
Wood Surfaces - Windows 2 finish coats		
Cost - Labor	\$ 5,000.00	\$ 4,800.00
Cost - Material	\$ 125.00	\$ 200.00
Number of Gallons	5	3
Ferrous Surfaces - Handrails, Raised foundation vents, 1 primer coat and 1 finish coat		
Cost - Labor	\$ 600.00	\$ 2,100.00
Cost - Material	\$ 100.00	\$ 400.00
Number of Gallons	2	8
Second finish coat		
Cost - Labor	\$ 300.00	\$ 300.00
Cost- Material	\$ 50.00	\$ 100.00
Number of Gallons	1	3
Steel/Ferrous Surfaces - Gates Top coat		
Cost - Labor	\$ 500.00	\$ 850.00
Cost - Material	\$ 45.00	\$ 50.00
Number of Gallons	1	1
Galvanized Surfaces - gutters, downspouts, roof vents, gable/attic vents, electrical panels, conduits 1 primer coat & 1 finish coat		
Cost - Labor	\$ 900.00	\$ 2,850.00
Cost - Material	\$ 100.00	\$ 250.00
Number of Gallons	4	5
Second finish coat		
Cost - Labor	\$ 300.00	\$ 350.00
Cost- Material	\$ 50.00	\$ 50.00
Number of Gallons	2	2
Gazebo - Post, Railings and Trim 1 primer & 1 finish coat		
Cost - Labor	\$ 680.00	\$ 2,500.00
Cost- Material	\$ 250.00	\$ 500.00
Number of Gallons	10	10
Second finish coat		
Cost - Labor	\$ 340.00	\$ 350.00
Cost- Material	\$ 125.00	\$ 150.00
Number of Gallons	6	5
Equipment Rental Aerial Work Platform/Lift		
	\$ 3,000.00	\$ 6,000.00
Total Labor	\$ 35,620.00	\$ 70,200.00
Total Material	\$ 6,195.00	\$ 14,100.00
Guarantee - Labor/Material	1 year	1 year
	No Subcontractors	No Subcontractors